

{ INTERVIEW } DAYS REFORE LAUNCH

Earlier mission was 'success-based': this one also factors in failures: Isro chief on Chandrayaan-3



Soumya Pillai

letters@hindustantimes.com NEW DELHI: Chandrayaan-3 has been designed keeping in mind everything that can go wrong. the chairman of Indian Space Research Organisation (Isro) has said, describing what he called as a switch to a "failurebased design" from the "success-based" approach of the last

moon mission spacecraft, which failed in landing intact.

Speaking to HT in an interview ahead of the Chandrayaan-3 launch scheduled on July 14. Isro chief S Somnath said the Indian space agency has perfected the part of reaching up to the moon. But it was the landing that the agency is working on.

"Instead of doing a successbased design, which we did in

Chandrayaan-2, we are going forward with a failure-based design for Chandrayaan-3. We have analysed all the things that can go wrong and have tried to prepare for it." he said.

The analysis from the Chan drayaan-2 mission, which launched on July 22, 2019 and eventually made what the space agency described as a "hard

continued on→15

tions to the trajectory on account of the excess thrust crecraft to turn", he said.

steady in order to take pictures.

spot that was still far away the course of its mobility. while it was already too close to the surface. The landing spot was limited to a 500metres x was trying to reach it by increasing its velocity. "There was a contradictory requirement of reaching the exact landing spot while also maintaining low velocity... In a nutshell, in Chandrayaan-2 the ability to handle parameter variation was limited and we have made corrections to that," he said.

Explaining some of the key corrections, Somnath added that the target landing spot has been expanded from a 500m x 500m patch to a 4km x 2.5km area "so that it will not limit the

craft to a small space". "We also increased fuel canacity so that it can move to an alternative landing site," he

Somnath said the scientific objective of the Chandrayaan-2 from its trajectory while "orbiter was already met, what of stability during a phase when was not met was the scientific the craft is supposed to be objective of the lander and rover".

Chandrayaan-3 consists of an The second was that correc- indigenous lander module, a propulsion module and a rover. Its objectives include developated a sort of "accumulation" of ing and demonstrating new problems that were dealt with technologies required for intertoo late, and the "the craft planetary missions. The lander started making very fast turns. will have the capability to soft This hampered the ability of the land at a specified lunar site and deploy the rover, which will The third was that the craft carry out in-situ chemical analwas trying to reach a landing ysis of the lunar surface during

This mission, the space agency chief said, will lay the foundation for another moon 500metres patch and the craft mission, the details of which will be announced later. "Isro is known for frugal engineering. We are known globally to successfully conduct exploratory missions at a much cheaper cost... We are in talks with the Japan Aerospace Exploration Agency (JAXA) for another moon mission. Details will be shared soon."

The Indian lunar exploration programme is an ongoing series of outer space missions by Isro. The first moon rocket, Chandrayaan-l, was launched in 2008, and was successfully inserted into lunar orbit.

Chandrayaan-2 was success fully launched and inserted into lunar orbit in 2019, but its lander "crash-landed" on the moon's surface when it deviated attempting to land on Septem ber 6, 2019, due to a software glitch

CHANDRAYAAN-3 landing" on September 6,

unearthed three mistakes that occurred

"The first challenge was that the five engines that were used for retardation (reduction of velocity), developed slightly higher thrust than was intended," he said, explaining added. that this excess led to a cascade of small problems that began accumulating, including a lack